

Appendix C. Setup Photographs

Spurious Radiation



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: U6M-SP3610 Page Number : C1 of C1
Report Issued Date : Mar. 11, 2008
Report Version : Rev. 01

Report No.: FG810406