

FCC ID: U88GSTR1930DT-SPR

ATTACHMENT F.

- INTERNAL PHOTOS -


SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 1/25





(Internal Photo)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 2/25





(10MHz IF Module FWD)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 3/25





(10MHz IF Module RVS)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 4/25





(15MHz IF Module FWD)



SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 5/25





(15MHz IF Module RVS)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 6/25





(20MHz IF Module FWD)



SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 7/25





(20MHz IF Module RVS)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 8/25





LNA MODULE (DONOR_FWD)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 9/25





LNA MODULE (DONOR_RVS)



SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 10/25





LNA MODULE (SERVICE_FWD)



SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 11/25





LNA MODULE (SERVICE_RVS)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 12/25





(Waveform Detector Top)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 13/25









Report No.: HCT-R07-013 14/25










Report No.: HCT-R07-013 15/25










Report No.: HCT-R07-013 16/25





(NMS Board Top)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 17/25





(NMS Board Bottom)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 18/25










Report No.: HCT-R07-013 19/25










Report No.: HCT-R07-013 20/25










Report No.: HCT-R07-013 21/25







Report No.: HCT-R07-013 22/25









Report No.: HCT-R07-013 23/25



FCC ID: U88GSTR1930DT-SPR

(Filter Bottom)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-013 24/25







Report No.: HCT-R07-013 25/25