

ATTACHMENT F.

- INTERNAL PHOTOGRAPHS -

Report No.: HCT-RF09-0116 1/32





Report No.: HCT-RF09-0116 2/32




WAVE MONITOR_800



Report No.: HCT-RF09-0116 3/32




WAVE MONITOR_1900



Report No.: HCT-RF09-0116 4/32




IF_10M_FWD



Report No.: HCT-RF09-0116 5/32




IF_10M_RVS



Report No.: HCT-RF09-0116 6/32



IF_15M_FWD



Report No.: HCT-RF09-0116 7/32




IF_15M_RVS



Report No.: HCT-RF09-0116 8/32



IF_20M_FWD



Report No.: HCT-RF09-0116 9/32



IF_20M_RVS



Report No.: HCT-RF09-0116 10/32



800_Converter Module



Report No.: HCT-RF09-0116 11/32




800_Converter Module



Report No.: HCT-RF09-0116 12/32




LAN MODULE_DONOR_FWD



Report No.: HCT-RF09-0116 13/32




LAN MODULE_DONOR_ RVS



Report No.: HCT-RF09-0116 14/32



LAN MODULE_SERVICE_FWD



Report No.: HCT-RF09-0116 15/32




LAN MODULE_SERVICE_RVS



Report No.: HCT-RF09-0116 16/32




Controller board_800_NMS BOARD_REAR



Report No.: HCT-RF09-0116 17/32




Controller board_800_NMS BOARD_FRONT



Report No.: HCT-RF09-0116 18/32




Controller board_1900 Controller_REAR



Report No.: HCT-RF09-0116 19/32




Controller board_1900 Controller_FRONT



Report No.: HCT-RF09-0116 20/32




800_LED_BOTTOM



Report No.: HCT-RF09-0116 21/32




800_LED_TOP



Report No.: HCT-RF09-0116 22/32




1900_LED_BOTTOM



Report No.: HCT-RF09-0116 23/32




1900_LED_TOP



Report No.: HCT-RF09-0116 24/32




800_PAM_FWD



Report No.: HCT-RF09-0116 25/32




800_PAM_RVS



Report No.: HCT-RF09-0116 26/32



1900_PAM_FWD



Report No.: HCT-RF09-0116 27/32




1900_PAM_RVS



Report No.: HCT-RF09-0116 28/32



800_IO BOARD_BOTTOM



Report No.: HCT-RF09-0116 29/32




800_IO BOARD_TOP



Report No.: HCT-RF09-0116 30/32




1900_ IO BOARD_ TOP



Report No.: HCT-RF09-0116 31/32



1900_IO BOARD_BOTTOM



Report No.: HCT-RF09-0116 32/32