

FCC ID: U88GSTR1937DT-SPR

ATTACHMENT F.

- INTERNAL PHOTOS -

SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-014 1/25





(Internal Photo)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-014 2/25










Report No.: HCT-R07-014 3/25










Report No.: HCT-R07-014 4/25









Report No.: HCT-R07-014 5/25





(15MHz IF Module RVS)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-014 6/25










7/25 Report No.: HCT-R07-014










Report No.: HCT-R07-014 8/25





LNA MODULE (DONOR_FWD)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-014 9/25





LNA MODULE (DONOR_RVS)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-014 10/25





LNA MODULE (SERVICE_FWD)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-014 11/25





LNA MODULE (SERVICE_RVS)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-014 12/25





(Waveform Detector Top)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-014 13/25










Report No.: HCT-R07-014 14/25








Report No.: HCT-R07-014 15/25








Report No.: HCT-R07-014 16/25





(NMS Board Top)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-014 17/25





(NMS Board Bottom)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-014 18/25





(IO Board Top)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-014 19/25



FCC ID: U88GSTR1937DT-SPR

(IO Board Bottom)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-014 20/25










Report No.: HCT-R07-014 21/25







Report No.: HCT-R07-014 22/25









Report No.: HCT-R07-014 23/25



FCC ID: U88GSTR1937DT-SPR

(Filter Bottom)



SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-014 24/25







Report No.: HCT-R07-014 25/25