

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U8G-P1813 Page Number : B1 of B2
Report Issued Date : Apr. 25, 2018
Report Version : Rev. 01


Report No.: FR820530B

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5



<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U8G-P1813 Page Number : B2 of B2
Report Issued Date : Apr. 25, 2018
Report Version : Rev. 01

Report No.: FR820530B

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5