

Appendix A. Test Photos

Report No.: FR461201AC

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No.: FR461201AC

1 Photographs of Conducted Emissions Test Configuration

Mode 1



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A6 TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report No.: FR461201AC



SIDE VIEW


SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report No.: FR461201AC

2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



: A4 of A6

: Rev. 01

REAR VIEW


SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version




FCC Test Report No.: FR461201AC

For radiated emissions 30MHz~1GHz

Mode 2



FRONT VIEW



: A5 of A6

: Rev. 01

REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version




FCC Test Report


Report No. : FR461201AC

For radiated emissions above 1GHz

Mode 1



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01