

LANCOM Systems

CANCOM Systems GmbB Adena renstraße 20782 52146 Worselen Deutschung Teleton --49 302405 49936 (I

www.ancom.do En niii into-dancom.de

Telefax +49 (0)2405 49936-99

Federal Communication Commission Equipment Authorization Division, Application Processing Branch 7435 Oakland Mills Road Columbia, MD 21048

23.05.2007

TO WHOM IT MAY CONCERN

Request for Change in Identification

Pursuant to CFR \S 2.933, **Hirschmann Automation and Control GmbH** hereby requests for change in identification.

This change is for application with FCC ID: U4Y-SE1I2 granted on 23.05.2007 The new FCC ID shall be U99BAT54RAIL

There are no changes in design, circuitry or construction. Therefore test results of the original grant continue to be representative of and applicable to the equipment bearing the changed identification.

The following new exhibits will be uploaded:

- External Photos
- ID label with label location information
- Authorization of the original grantee

If you have any questions, please feel free to contact us at the address shown below

Sincerely,

Udo Brocker, Director Development and IT

LANCOM Systems GmbH Adenauerstr. 20/B2 52146 Würselen, Germany +49 2405 49936 0

Udo Brown