

EXTERNAL PHOTOGRAPHS ANNEX C



100984_a.jpg: BAT300-Rail FCC (Host), 3-D view 1

Test engineer: Thomas KÜHN
Date of issue: 02 September 2010 Report Number: Order Number: F100984E2 page 1 of 7






100984_b.jpg: BAT300-Rail FCC (Host), 3-D view 2

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 2 of 7






100984_k.jpg: BAT300-Rail FCC (Host), type plate 1

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 3 of 7





100984_I.jpg: BAT300-Rail FCC (Host), type plate 2

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 4 of 7





100984_m.jpg: BAT300-F FCC (Host), 3-D view 1

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 5 of 7






100984_n.jpg: BAT300-F FCC (Host), 3-D view 2

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 6 of 7





100984_o.jpg: BAT300-F FCC (Host), type plate

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 7 of 7