


FCC Test Report No.: EP471515

## APPENDIX B. Photographs of EUT






TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B1 OF B11
ISSUED DATE : Oct. 07, 2014














































TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B6 OF B11
ISSUED DATE : Oct. 07, 2014

















SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B8 OF B11
ISSUED DATE : Oct. 07, 2014










TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B9 OF B11
ISSUED DATE : Oct. 07, 2014











SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B11 OF B11
ISSUED DATE : Oct. 07, 2014