

Appendix A. Test Photos

Report No. : FR471515

SPORTON INTERNATIONAL INC. Page No. : A1 of A10 TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report **Report No. : FR471515**

1 Photographs of Conducted Emissions Test Configuration

Mode 1



FRONT VIEW



: A2 of A10

: Rev. 01

REAR VIEW

SPORTON INTERNATIONAL INC. Page No. Report Version

TEL: 886-3-327-3456 FAX: 886-3-327-0973





SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A10 TEL: 886-3-327-3456 Report Version : Rev. 01




CC Test Report Report No.: FR471515

Mode 3



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A10

: Rev. 01

Report Version






SPORTON INTERNATIONAL INC. Page No. : A5 of A10 TEL: 886-3-327-3456 Report Version : Rev. 01



2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A10 TEL: 886-3-327-3456 Report Version : Rev. 01




For radiated emissions 30MHz~1GHz

Mode 1



FRONT VIEW




REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A7 of A10 TEL: 886-3-327-3456 Report Version : Rev. 01



Mode 4



FRONT VIEW



: A8 of A10

: Rev. 01


REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version




For radiated emissions above 1GHz

Mode 1



FRONT VIEW




REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A9 of A10 TEL: 886-3-327-3456 Report Version : Rev. 01



Mode 4



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A10 of A10

Report Version

: Rev. 01