


APPENDIX B. Photographs of EUT





TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B1 OF B8
FCC ID : U9YAL5616







SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B2 OF B8
FCC ID : U9YAL5616


FCC TEST REPORT NO.: FR011911






TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B3 OF B8 FCC ID : U9YAL5616






SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B4 OF B8 FCC ID : U9YAL5616






SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B5 OF B8 FCC ID : U9YAL5616






SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255





SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B7 OF B8 FCC ID : U9YAL5616 FCC TEST REPORT



SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B8 OF B8 FCC ID : U9YAL5616