

20575 NW Von Neumann Drive, Suite 100 Beaverton, OR 97006 USA

Phone: 503 615-7700 • Fax: 503 615-4232

http://www.summitsemi.com

7 December, 2015

Federal Communications Commission Authorization and Evaluation Branch 7435 Oakland Mills Road Columbia, MD 21046

To Whom it May Concern:

We attest to the following:

- Per FCC KDB 905462 D03 v01r01, the device is a client device with no radar detection capability. The client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master. This includes restriction on transmissions for beacons and support for ad-hoc peer-to-peer modes.
- Per FCC KDB 594280 D01 v02r01, the device complies with the requirements for software configuration control. The device meets the definition of FCC 15.202 client device and does not have the ability to be configured by end users or professional installers to operate outside the authorized bands
- Per FCC 15.407(c), the device will automatically discontinue transmission in case of either absence of information to transmit or operational failure.

Sincerely,

Kenneth A. Boehlke Principal Engineer

Zuneth A. Boehler