





### **Inside View of The EUT**




Report no. ETLE060517.220, Page 1 of 10







### **Component side view of Main board**




Report no. ETLE060517.220, Page 2 of 10







### Solder side view of Main board




Report no. ETLE060517.220, Page 3 of 10








### **Inside View of The LNB TUNER**





Report no. ETLE060517.220, Page 4 of 10







### **Component side view of Power board**




Report no. ETLE060517.220, Page 5 of 10







### Solder side view of Power board



Report no. ETLE060517.220, Page 6 of 10








### **Component side view of Front Board**



### **Solder side view of Front Board**



Report no. ETLE060517.220, Page 7 of 10








### **Inside View of The EUT of RF Modulator**





Report no. ETLE060517.220, Page 8 of 10





#### **View of Bottom cover**



#### **View of Top cover**



Report no. ETLE060517.220, Page 9 of 10







### **View of Front Cover**



### **View of Remote Control Unit**



Report no. ETLE060517.220, Page 10 of 10

EMC Lab : #584 Sangwhal-ri, Ganam-myeon, Yoju-gun, Gyounggi-do, 469-885, Korea Tel:82-31-885-0072, Fax:82-31-885-0074 ETLQP-21-F22-0