

Appendix C. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: UB4CS508 Page Number : C1 of C3
Report Issued Date : Jul. 22, 2015
Report Version : Rev. 01

Report No.: FR562601





Report No. : FR562601

<Radiated Emission>

Y Plane

LF





HF


SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: UB4CS508 Page Number : C2 of C3
Report Issued Date : Jul. 22, 2015
Report Version : Rev. 01





Report No. : FR562601



Near side

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: UB4CS508

Page Number : C3 of C3 Report Issued Date: Jul. 22, 2015

Report Version : Rev. 01