宁波音王集团有限公司

Ningbo Soundking Group Co., Ltd.

FCCID: UBTEW019

November. 20. 2008 Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia MD 21046

I would like to confirm this device (FCC ID: UBTEW019) does not have tune up information because the tune up is fixed by the manufacturer. Therefore, the user cannot tune up the device.

Sincerely,

Ningbo Soundking Group Co., Ltd.

Yingchun Xie