


FCC ID : UBUITWELL-XPDA-S Report File No. : STROR-07-024 Page : 39 of 46

Inner View of EUT



Bottom of CDMA Module (Removal shield cap)





FCC ID : UBUITWELL-XPDA-S Report File No. : STROR-07-024 Page : 40 of 46

Top of CDMA Module (Removal shield cap)



Top of CDMA Module main-board





FCC ID : UBUITWELL-XPDA-S Report File No. : STROR-07-024 Page : 41 of 46

Bottom of CDMA Module main-board



Inner View of EUT





FCC ID : UBUITWELL-XPDA-S Report File No. : STROR-07-024 Page : 42 of 46

Inner View of EUT



Top View of Scanner






FCC ID : UBUITWELL-XPDA-S Report File No. : STROR-07-024 Page : 43 of 46

Bottom View of Scanner



Top View of Main-Board





FCC ID : UBUITWELL-XPDA-S Report File No. : STROR-07-024 Page : 44 of 46

Bottom View of Main-Board



Top View of CPU





FCC ID : UBUITWELL-XPDA-S Report File No. : STROR-07-024 Page : 45 of 46

Bottom View of CPU




Bottom View of Key pad





FCC ID : UBUITWELL-XPDA-S Report File No. : STROR-07-024 Page : 46 of 46

Top View of Key pad



Inner View of LCD panel

