


Setup Photographs

<Conducted Emission>



Remote View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UCE216065A Page Number : 1 of 3
Report Issued Date : Aug. 18, 2016
Report Version : Rev. 01

Report No.: FR671309C

Report Template No.: BU5-FR15CWL Version 1.3







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UCE216065A Page Number : 2 of 3
Report Issued Date : Aug. 18, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3




<Radiated Emission>

Y Plane

LF





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UCE216065A

: 3 of 3 Page Number Report Issued Date: Aug. 18, 2016 : Rev. 01 Report Version

Report No.: FR671309C

Report Template No.: BU5-FR15CWL Version 1.3