

Setup Photographs

<Conducted Emission>

<Original Test>



Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UCE216065A Page Number : 1 of 4
Report Issued Date : Aug. 29, 2016
Report Version : Rev. 02

Report No.: FR671309D

Report Template No.: BU5-FR15CNFC Version 1.0





Rear View

<Terminal Test>



Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UCE216065A Page Number : 2 of 4
Report Issued Date : Aug. 29, 2016
Report Version : Rev. 02

Report No.: FR671309D

Report Template No.: BU5-FR15CNFC Version 1.0







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UCE216065A Page Number : 3 of 4
Report Issued Date : Aug. 29, 2016
Report Version : Rev. 02


Report Template No.: BU5-FR15CNFC Version 1.0



<Radiated Emission>

Y Plane

From 9 kHz~30MHz



From 30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UCE216065A Page Number : 4 of 4
Report Issued Date : Aug. 29, 2016
Report Version : Rev. 02
Report Template No.: BU5-FR15CNFC Version 1.0

Report No.: FR671309D