

Setup Photographs

<Conducted Emission>




Remote View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UCE216065A Page Number : 1 of 3
Report Issued Date : Aug. 26, 2016
Report Version : Rev. 02

Report No.: FR671309A

Report Template No.: BU5-FR15CBT Version 1.1





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UCE216065A Page Number : 2 of 3
Report Issued Date : Aug. 26, 2016
Report Version : Rev. 02


Report Template No.: BU5-FR15CBT Version 1.1



<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UCE216065A Page Number : 3 of 3
Report Issued Date : Aug. 26, 2016
Report Version : Rev. 02
Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR671309A