


## Appendix E - Test Setup Photos



Backside of the DUT with Phantom 0 cm Gap

Bottom of the DUT with Phantom 0 cm Gap

Report No.: FA962008

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UCV-HDS100 Report Issued Date: Jul. 02, 2009
Report Version: Rev. 01