


# Appendix C. Photographs of Setup

## **Conducted Emission**

Mode 1



**FRONT VIEW** 



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UCVHSTNH-F16C Page No. : C1 of C6
Report Issued Date : Aug. 09, 2007
Report Version : Rev. 01





SIDE VIEW

#### Mode 2




FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UCVHSTNH-F16C Page No. : C2 of C6
Report Issued Date : Aug. 09, 2007
Report Version : Rev. 01





**REAR VIEW** 



SIDE VIEW

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UCVHSTNH-F16C Page No. : C3 of C6

Report Issued Date : Aug. 09, 2007



## **Radiation Emission**

### Mode 1-6



FRONT VIEW

SPORTON International Inc.


TEL: 886-2-2696-2468

FAX: 886-2-2696-2255

FCC ID: UCVHSTNH-F16C


Page No. : C4 of C6

Report Issued Date : Aug. 09, 2007



**REAR VIEW** 

#### Mode 7-15



FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UCVHSTNH-F16C Page No. : C5 of C6
Report Issued Date : Aug. 09, 2007





**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468

FAX: 886-2-2696-2255

FCC ID: UCVHSTNH-F16C

Page No. : C6 of C6

Report Issued Date : Aug. 09, 2007