




Appendix F. Test Photos

1. Photographs of Conducted Emissions Test Configuration
<Adapter MODE>



Report No.: FR640901AC

FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : F1 of F5 TEL: 886-3-327-3456 Report Version : Rev. 02







Report No.: FR640901AC

SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : F2 of F5
TEL: 886-3-327-3456 Report Version : Rev. 02



Report No.: FR640901AC FCC Test Report

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : F3 of F5 TEL: 886-3-327-3456 Report Version : Rev. 02




FCC Test Report

Report No.: FR640901AC

For radiated emissions 30MHz~1GHz <Adapter MODE>



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F4 of F5

Report Version


: Rev. 02




FCC Test Report

Report No.: FR640901AC

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : F5 of F5
TEL: 886-3-327-3456 Report Version : Rev. 02