


Report No. : FA480825

Appendix D. SAR Test Setup Photos



Rear Face

SPORTON INTERNATIONAL INC. Page No. : A1 of A1
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973