Test report No. : 26HE0264-HO-A-1

Page : 9 of 16


Issued date : July 3, 2006


Revised data : July 5, 2006

FCC ID : UDFRC441-9315

APPENDIX 1: Photographs of test setup

Radiated Emission





UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 26HE0264-HO-A-1
Page : 10 of 16
Issued date : July 3, 2006
Revised data : July 5, 2006
FCC ID : UDFRC441-9315

Worst Case Position (X-axis)



Y-axis



Z-axis



UL Apex Co., Ltd. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124