Dear Tim, Also pleas

Also please kindly check if they were ok or not, thanks.

- 1) We have remove the band of 5150-5250 MHz, and update the test report, manual, RF exposure, Operational Description and 731 form in the attachment;
- 2) We have added the both antennas together for the RF exposures in the attachment;
- 3) We retest the the conducted Band Edge and update the test report in the attachment;
- 4) We corrected by User Manual of Page 9;
- 5) We have modify the User Manual of page 12, and let the manufacturer modify the software for "USA Use Only";

best regards, Jewel