

Tel.: +82-31-500-0133

Fax.: +82-31-500-0159



SAR Measurement Setup Photos UM100





$Test\ Sample\ Photo-UM100$



<close>



<open>







<front>




<rear>







<left side>



<right side>







<top>



Fax.: +82-2-860-1468



HP Compaq nc2400



<close>



<open>



Fax.: +82-2-860-1468



Body SAR setup photos



<Horizontal up>



<Horizontal down>







<Vertical up>



<Vertical down>







<Top>



<USB Cable>