Chris Harvey

□□□ [skcho@ktl.re.kr] From:

Tuesday, June 24, 2008 8:22 AM Sent: charvey-tcb@ccsemc.com To:

lucy.tsai@ccsemc.com; banjg@ktl.re.kr Cc:

Subject: RE: Uriver Inc., FCC ID: UDTUR80, Assessment NO.: AN08T7985, Notice#1

USER Manual.pdf; Internal photo.pdf; 2008-341-031-1 UR801 SAR Report.pdf; Calibration **Attachments:**

Data Sheets-#1.pdf; Calibration Data Sheets-#2.pdf; UR801 SAR POLTS.pdf













JSER Manual.pdf (2 Internal photo.pdf 2008-341-031-1 (487 KB)

Calibration Data UR801 SAR Repor... Sheets-#1.pdf...

Calibration Data Sheets-#2.pdf...

UR801 SAR POLTS.pdf (1 MB)

Dear Chris,

My answer is embeded below. Thankyou.

----Original Message----

From: charvey-tcb@ccsemc.com [mailto:charvey-tcb@ccsemc.com]

Sent: Saturday, June 21, 2008 4:14 AM

To: skcho@ktl.re.kr

Cc: charvey-tcb@ccsemc.com; lucy.tsai@ccsemc.com

Subject: Uriver Inc., FCC ID: UDTUR80, Assessment NO.: AN08T7985, Notice#1

Dear SK Cho,

You are listed as the Technical Contact for the above referenced TCB application. The following item(s) need(s) to be resolved before the review can be continued:

Please note that the PC Peripheral Test Report (15-B) is not required to be submitted in this Certification application since it is being DoC approved. I have not reviewed the PC Peripheral Test Report and will remove it from this application.

1. The FCC has recently updated the policy of simultaneous transmission in handsets by eliminating the simultaneous transmission during SAR compliance testing. Testing with a Bluetooth transmitter on while testing a handset primary transmitter is no longer considered a valid test by the FCC.

Instead, the devices transmitters and relative antenna placement is evaluated to determine what type of RF Exposure evaluation is required.

Please re-evaluate this device to determine if RF Exposure during simultaneous transmission is required and amend the SAR report according to the new procedure in FCC KDB# 648474:

https://fjallfoss.fcc.gov/oetcf/kdb/forms/FTSSearchResultPage.cfm?id=33853&s witch=P

"When stand-alone SAR evaluation is not required and the antenna is \square 5 cm from other antennas, simultaneous transmission SAR evaluation is also not required for that antenna." [Sung-kyu Cho] I attached revised SAR test report and cal data sheets & SAR plots.

2. The Users Manual has a location to include the FCC ID on page 10, but the FCC ID has not been included. The FCC requires that if the FCC ID number is referenced in the Manual that it must be correct. Please either include the FCC ID number correctly in the manual or remove the reference.

[Sung-kyu Cho] I attached revised User manual.

3. The internal photos seem to show only one side of the Bluetooth transmission board. Also, there are no photos of the general construction of the handset with the cover removed. Please update the internal Photos exhibit. [Sung-kyu Cho] I attached revised Internal photo.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best regards,

Chris Harvey Charvey-tcb@ccsemc.com