


1. Photographs of Conducted Emissions Test Configuration



Front view




Side view

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 4
EP Report Version : Rev. 01
Issued Date : Feb. 05, 2018






**Under Table View** 

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 2 of 4
EP Report Version : Rev. 01
Issued Date : Feb. 05, 2018



# 2. Photographs of Radiated Emissions Test Configuration For radiated emissions below 1G



Front view



Rear view

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973

: 3 of 4 Page No. EP Report Version : Rev. 01 Issued Date : Feb. 05, 2018



#### For radiated emissions above 1GHz



#### Front view



#### Rear view

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 4 of 4
EP Report Version : Rev. 01
Issued Date : Feb. 05, 2018