




1. Photographs of Conducted Emissions Test Configuration



Report No.: FR851627AL

Front view



Side view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 4
Report Version : Rev. 01







Report No.: FR851627AL

Under Table View

SPORTON INTERNATIONAL INC. Page No TEL: 886-3-327-3456 Report V

FAX: 886-3-327-0973

Page No. : 2 of 4
Report Version : Rev. 01




Test Setup Photos

Report No.: FR851627AL

2. Photographs of Radiated Emissions Test Configuration For radiated emissions below 1G

PIFA Antenna



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 3 of 4 Report Version : Rev. 01



Test Setup Photos

Report No.: FR851627AL

For radiated emissions above 1GHz



Front view



Rear view

----THE END----

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 4 of 4
Report Version : Rev. 01