

Test Setup Photos

1. Photographs of Conducted Emissions Test Configuration



Front view




Side view

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 4
EP Report Version : Rev. 01
Issued Date : Sep. 18, 2018



Test Setup Photos



Under Table View

 SPORTON International Inc.
 Page No.
 : 2 of 4


 TEL: 886-3-327-3456
 EP Report Version
 : Rev. 01

 FAX: 886-3-327-0973
 Issued Date
 : Sep. 18, 2018





2. Photographs of Radiated Emissions Test Configuration For radiated emissions below 1G



Front view



Rear view


SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 3 of 4 EP Report Version : Rev. 01 Issued Date : Sep. 18, 2018




Test Setup Photos

For radiated emissions above 1GHz



Front view



Rear view

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 4 of 4
EP Report Version : Rev. 01
Issued Date : Sep. 18, 2018