


Test Setup Photos Report No. : CR851627AD

1. Photographs of Conducted Emissions Test Configuration



Front view



Side view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 4
Report Version : Rev. 01







Report No. : CR851627AD

**Under Table View** 

SPORTON INTERNATIONAL INC. Page No. : 2 of 4
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973



## **Test Setup Photos**

Report No.: CR851627AD

## 2. Photographs of Radiated Emissions Test Configuration For radiated emissions below 1G

**PIFA Antenna** 



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 3 of 4 Report Version : Rev. 01




## **Test Setup Photos**

Report No.: CR851627AD

## For radiated emissions above 1GHz



Front view



Rear view

——THE END——

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 4 of 4
Report Version : Rev. 01