


1. Photographs of Conducted Emissions Test Configuration



Front view




Side view

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 4
EP Report Version : Rev. 01
Issued Date : Sep. 18, 2018





**Under Table View** 


SPORTON International Inc. Page No. EP Report Version : Rev. 01 TEL: 886-3-327-3456

FAX: 886-3-327-0973 Issued Date : Sep. 18, 2018

: 2 of 4



# 2. Photographs of Radiated Emissions Test Configuration For radiated emissions below 1G



Front view




Rear view

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 3 of 4 EP Report Version : Rev. 01 Issued Date : Sep. 18, 2018



### For radiated emissions above 1GHz



#### Front view



#### Rear view

----THE END-----

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 4 of 4
EP Report Version : Rev. 01
Issued Date : Sep. 18, 2018