


## Test Setup Photos

## 1. Photographs of Test Configuration



**Front View** 

 SPORTON International Inc.
 Page No.
 : 1 of 1

 TEL: 886-3-327-3456
 EP Report Version
 : Rev. 01

 FAX: 886-3-327-0973
 Issued Date
 : Feb. 05, 2018