


SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 148 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

Page No. : 149 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 150 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018





SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 151 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018

68.20

Inf



PK

5.4684G

5.5512G

59.30

102.55

802.11ac VHT40\_Nss1,(MCS0)\_2TX 5550MHz TX Lim.PK 120 -PK Lim.AV  $| \Delta \rangle$ 100-A۷ 80 -60 -40 -20 5.4G 5.42G 5.44G 5.46G 5.48G 5.5G 5.52G 5.54G 5.56G 5.58G 5.62G 5.64G 5.66G 5.68G 5.7G 20170831 EUT Z\_2TX Setting 21 02-J-6-10 FSU Level(dBuV/m) Limit(dBuV/m) Margin(dB) Factor(dB) Type Freq(Hz) Dist(m) Pol.(H/V) Azimuth(°) Height(m) Comments ΑV 5.4558G 47.22 54.00 -6.78 9.67 176 1.40 5.5518G 92.88 -Inf 1.40 PK 5.4522G 59.80 74.00 -14.20 9.66 3 ٧ 176 1.40

9.70

9.84

3

3

-8.90

-Inf

176

176

1.40


1.40

SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 152 of 256
Report Version : Rev. 03
Issued Date : Jan. 12, 2018

Report No.: FR782229AC






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 153 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 154 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 155 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 156 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 157 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 158 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 159 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

: 160 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 161 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 162 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 163 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

: 164 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 165 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 166 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018





SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 167 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018




802.11ac VHT80\_Nss1,(MCS0)\_2TX 5530MHz\_TX Lim.PK 120 -PK Lim.AV  $| \wedge \rangle$ 100 -80 -60 -40 -20 -0-5.28G 5.35G 5.5G 5.55G 5.6G 5.65G 5.7G 5.4G 5.45G 5.75G 5.78G 20170831 EUT Z\_2TX Setting 16.5 02-J-6-10 FSU Type Freq(Hz) Level(dBuV/m) Limit(dBuV/m) Margin(dB) Factor(dB) Dist(m) Pol.(H/V) Azimuth(°) Height(m) Comments A۷ 5.458G 47.76 54.00 -6.24 9.68 237 1.33 A۷ 5.538G 83.42 Inf -Inf 9.82 3 ٧ 237 1.33 PK 5.455G 74.00 -14.39 9.67 3 ٧ 237 1.33 59.61 PK 5.461G 59.19 68.20 -9.01 9.68 3 237 1.33 PK 5.538G 92.66 Inf -Inf 9.82 3 ٧ 237 1.33 PK 5.741G 68.20 -8.81 9.91 3 237 1.33 59.39

SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 168 of 256
Report Version : Rev. 03
Issued Date : Jan. 12, 2018

Report No.: FR782229AC






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

: 169 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 170 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 171 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 172 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

: 173 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 174 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 175 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

: 176 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018





SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 177 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018



802.11ac VHT80\_Nss1,(MCS0)\_2TX 5690MHz Straddle 5.47-5.725GHz\_TX



20170831 EUT Z\_2TX Setting 23 02-J-6 FSU


Туре	Freq(Hz)	Level(dBuV/m)	Limit(dBuV/m)	Margin(dB)	Factor(dB)	Dist(m)	Pol.(H/V)	Azimuth(°)	Height(m)	Comments
ΑV	11.38022G	41.63	54.00	-12.37	16.24	3	V	290	1.53	-
PK	11.38092G	54.53	74.00	-19.47	16.25	3	V	290	1.53	-

SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 178 of 256
Report Version : Rev. 03
Issued Date : Jan. 12, 2018

Report No.: FR782229AC






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 179 of 256
Report Version : Rev. 03
Issued Date : Jan. 12, 2018

Report No.: FR782229AC






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 180 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 181 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 183 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 184 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 185 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 186 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 187 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

Page No. : 188 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

Page No. : 189 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 190 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 191 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

: 192 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 193 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 194 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 195 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 196 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 197 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 198 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 199 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 200 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

: 201 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 202 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 203 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 204 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 205 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018



802.11ac VHT20-BF\_Nss1,(MCS0)\_2TX



20170831 EUT Z\_2TX Setting 21 (Max setting) 02-J-6-10 FSU


Type	Freq(Hz)	Level(dBuV/m)	Limit(dBuV/m)	Margin(dB)	Factor(dB)	Dist(m)	Pol.(H/V)	Azimuth(°)	Height(m)	Comments
ΑV	11.44772G	42.41	54.00	-11.59	16.32	3	V	359	2.43	-
PK	11.43428G	56.01	74.00	-17.99	16.30	3	V	359	2.43	-
PK	17.15804G	66.34	68.20	-1.86	21.83	3	V	295	1.00	-

SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 206 of 256
Report Version : Rev. 03
Issued Date : Jan. 12, 2018

Report No.: FR782229AC






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 207 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 208 of 256
Report Version : Rev. 03
Issued Date : Jan. 12, 2018

Report No.: FR782229AC






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 209 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 210 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 211 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 212 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 213 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 214 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 215 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 216 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

Page No. : 217 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 218 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

Page No. : 219 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018





SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 220 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018



FSU


802.11ac VHT40-BF\_Nss1,(MCS0)\_2TX 5550MHz\_TX Lim.PK 120 -PK Lim.AV  $\wedge$ 100 -A۷ 80 -60 -40 -20 -5.4G 5.42G 5.44G 5.46G 5.48G 5.5G 5.52G 5.54G 5.56G 5.58G 5.62G 5.62G 5.64G 5.66G 5.68G 5.7G 20170901 EUT Z\_2TX Setting 21 02-Z-1-10

Type	Freq(Hz)	Level(dBuV/m)	Limit(dBuV/m)	Margin(dB)	Factor(dB)	Dist(m)	Pol.(H/V)	Azimuth(°)	Height(m)	Comments
ΑV	5.424G	47.40	54.00	-6.60	9.58	3	Н	246	1.02	-
ΑV	5.5416G	97.32	Inf	-Inf	9.83	3	Н	246	1.02	-
PK	5.4096G	60.04	74.00	-13.96	9.55	3	Н	246	1.02	-
PK	5.4624G	59.12	68.20	-9.08	9.69	3	Н	246	1.02	-
PK	5.5374G	108.55	Inf	-Inf	9.82	3	Н	246	1.02	-

SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 221 of 256
Report Version : Rev. 03
Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 222 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 223 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

Page No. : 224 of 256
Report Version : Rev. 03
Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

Page No. : 225 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

Page No. : 226 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 227 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 228 of 256
Report Version : Rev. 03
Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 229 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 230 of 256 Page No. Report Version : Rev. 03 : Jan. 12, 2018 Issued Date






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 231 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 232 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 233 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 234 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 235 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 236 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

FAX: 886-3-3270973 FCC ID: UDX-60067010

TEL: 886-3-3273456

: 237 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 238 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 239 of 256 Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 240 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 241 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 242 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 243 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 244 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010

: 245 of 256 Page No. Report Version : Rev. 03 Issued Date : Jan. 12, 2018






SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010





SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973 FCC ID: UDX-60067010

: 247 of 256 Page No. Report Version : Rev. 03 : Jan. 12, 2018 Issued Date

## 3.6 Frequency Stability

## 3.6.1 Frequency Stability Limit

#### **Frequency Stability Limit**

Report No.: FR782229AC

#### **UNII Devices**

 In-band emission is maintained within the band of operation under all conditions of normal operation as specified in the user's manual.

#### **LE-LAN Devices**

N/A

#### IEEE Std. 802.11

■ The transmitter center frequency tolerance shall be ± 20 ppm maximum for the 5 GHz band and ± 25 ppm maximum for the 2.4 GHz band.

#### 3.6.2 Measuring Instruments


Refer a test equipment and calibration data table in this test report.

#### 3.6.3 Test Procedures

#### **Test Method**

- Refer as ANSI C63.10, clause 6.8 for frequency stability tests
  - Frequency stability with respect to ambient temperature
  - Frequency stability when varying supply voltage
  - Extreme temperature is -20°C~50°C.

## 3.6.4 Test Setup



 SPORTON INTERNATIONAL INC.
 Page No.
 : 248 of 256

 TEL: 886-3-3273456
 Report Version
 : Rev. 03

 FAX: 886-3-3270973
 Issued Date
 : Jan. 12, 2018

FCC ID: UDX-60067010



FCC Test Report No.: FR782229AC

# 3.6.5 Test Result of Frequency Stability

Mode: 20 MHz / Ant. 2

Voltage vs. Frequency Stability

Voltage	Measurement Frequency (MHz)				
(V)	5300 MHz				
(V)	0 Minute	2 Minute	5 Minute	10 Minute	
126.50	5299.9659	5299.9658	5299.9653	5299.9652	
110.00	5299.9655	5299.9648	5299.9642	5299.9634	
93.50	5299.9645	5299.9636	5299.9630	5299.9625	
Max. Deviation (MHz)	0.0355	0.0364	0.0370	0.0375	
Max. Deviation (ppm)	6.70	6.87	6.98	7.08	
Result	Pass				

Temperature vs. Frequency Stability

Temperature	Measurement Frequency (MHz)						
(℃)	5300 MHz						
(C)	0 Minute	2 Minute	5 Minute	10 Minute			
-20	5299.9608	5299.9601	5299.9593	5299.9584			
-10	5299.9617	5299.9615	5299.9610	5299.9601			
0	5299.9622	5299.9617	5299.9609	5299.9608			
10	5299.9640	5299.9638	5299.9629	5299.9628			
20	5299.9655	5299.9654	5299.9644	5299.9636			
30	5299.9958	5299.9951	5299.9946	5299.9936			
40	5299.9960	5299.9957	5299.9953	5299.9948			
50	5299.9976	5299.9966	5299.9964	5299.9963			
Max. Deviation (MHz)	0.0392	0.0399	0.0407	0.0416			
Max. Deviation (ppm)	7.40	7.53	7.68	7.85			
Result		Pa	iss	Pass			

 SPORTON INTERNATIONAL INC.
 Page No.
 : 249 of 256

 TEL: 886-3-3273456
 Report Version
 : Rev. 03

 FAX: 886-3-3270973
 Issued Date
 : Jan. 12, 2018

FCC ID: UDX-60067010



## Voltage vs. Frequency Stability

Voltage	Measurement Frequency (MHz)				
() ()		5580 MHz			
(V)	0 Minute	2 Minute	5 Minute	10 Minute	
126.50	5579.9663	5579.9653	5579.9644	5579.9640	
110.00	5579.9655	5579.9645	5579.9640	5579.9634	
93.50	5579.9646	5579.9639	5579.9633	5579.9627	
Max. Deviation (MHz)	0.0354	0.0361	0.0367	0.0373	
Max. Deviation (ppm)	6.34	6.47	6.58	6.68	
Result	Pass				

## Temperature vs. Frequency Stability

Temperature	Measurement Frequency (MHz)				
(℃)	5580 MHz				
(0)	0 Minute	2 Minute	5 Minute	10 Minute	
-20	5579.9598	5579.9594	5579.9592	5579.9585	
-10	5579.9615	5579.9614	5579.9612	5579.9604	
0	5579.9629	5579.9622	5579.9615	5579.9613	
10	5579.9648	5579.9647	5579.9643	5579.9639	
20	5579.9655	5579.9650	5579.9646	5579.9638	
30	5579.9958	5579.9957	5579.9953	5579.9947	
40	5579.9968	5579.9958	5579.9957	5579.9950	
50	5579.9976	5579.9967	5579.9958	5579.9948	
Max. Deviation (MHz)	0.0402	0.0406	0.0408	0.0415	
Max. Deviation (ppm)	7.20	7.28	7.31	7.44	
Result		Pass			

SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 250 of 256
Report Version : Rev. 03

Issued Date : Jan. 12, 2018



Mode: 40 MHz / Ant. 2

## Voltage vs. Frequency Stability

Voltage	Measurement Frequency (MHz)				
(V)		5310 MHz			
(V)	0 Minute	2 Minute	5 Minute	10 Minute	
126.50	5309.9660	5309.9656	5309.9654	5309.9644	
110.00	5309.9655	5309.9650	5309.9648	5309.9646	
93.50	5309.9648	5309.9647	5309.9645	5309.9644	
Max. Deviation (MHz)	0.0352	0.0353	0.0355	0.0356	
Max. Deviation (ppm)	6.63	6.65	6.69	6.70	
Result	Pass				

Temperature vs. Frequency Stability

Temperature		Measurement Frequency (MHz)				
(°C)	5310 MHz					
(0)	0 Minute	2 Minute	5 Minute	10 Minute		
-20	5309.9633	5309.9629	5309.9628	5309.9620		
-10	5309.9635	5309.9633	5309.9628	5309.9623		
0	5309.9642	5309.9636	5309.9631	5309.9627		
10	5309.9646	5309.9643	5309.9642	5309.9639		
20	5309.9655	5309.9646	5309.9641	5309.9632		
30	5309.9958	5309.9957	5309.9956	5309.9954		
40	5309.9970	5309.9960	5309.9958	5309.9951		
50	5309.9670	5309.9662	5309.9656	5309.9647		
Max. Deviation (MHz)	0.0367	0.0371	0.0372	0.0380		
Max. Deviation (ppm)	6.91	6.99	7.01	7.16		
Result		Pass				

SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No.
Report Version

: 251 of 256 : Rev. 03

Issued Date

: Jan. 12, 2018



## Voltage vs. Frequency Stability

Voltage	Measurement Frequency (MHz)					
0.0		5550 MHz				
(V)	0 Minute	2 Minute	5 Minute	10 Minute		
126.50	5549.9660	5549.9654	5549.9650	5549.9644		
110.00	5549.9655	5549.9647	5549.9643	5549.9633		
93.50	5549.9650	5549.9646	5549.9636	5549.9628		
Max. Deviation (MHz)	0.0350	0.0354	0.0364	0.0372		
Max. Deviation (ppm)	6.31	6.38	6.56	6.70		
Result	Pass					

Temperature vs. Frequency Stability

Temperature	Measurement Frequency (MHz)				
(°C)	5550 MHz				
(℃)	0 Minute	2 Minute	5 Minute	10 Minute	
-20	5549.9616	5549.9607	5549.9601	5549.9600	
-10	5549.9629	5549.9623	5549.9618	5549.9616	
0	5549.9640	5549.9634	5549.9630	5549.9622	
10	5549.9647	5549.9643	5549.9637	5549.9628	
20	5549.9655	5549.9654	5549.9650	5549.9645	
30	5549.9958	5549.9954	5549.9947	5549.9937	
40	5549.9974	5549.9970	5549.9968	5549.9964	
50	5549.9667	5549.9658	5549.9648	5549.9646	
Max. Deviation (MHz)	0.0384	0.0393	0.0399	0.0400	
Max. Deviation (ppm)	6.92	7.08	7.19	7.21	
Result	Pass				

SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No.

: 252 of 256 : Rev. 03

Report No.: FR782229AC

Report Version Issued Date

: Jan. 12, 2018



# FCC Test Report No.: FR782229AC

Mode: 80 MHz / Ant. 2

Voltage vs. Frequency Stability

Voltage	Measurement Frequency (MHz)				
00	5290 MHz				
(V)	0 Minute	2 Minute	5 Minute	10 Minute	
126.50	5289.9662	5289.9655	5289.9648	5289.9644	
110.00	5289.9655	5289.9650	5289.9642	5289.9633	
93.50	5289.9651	5289.9648	5289.9646	5289.9642	
Max. Deviation (MHz)	0.0349	0.0352	0.0358	0.0367	
Max. Deviation (ppm)	6.60	6.65	6.77	6.94	
Result	Pass				

Temperature vs. Frequency Stability

Temperature	Measurement Frequency (MHz)					
(℃)		5290 MHz				
(0)	0 Minute	2 Minute	5 Minute	10 Minute		
-20	5289.9604	5289.9596	5289.9592	5289.9584		
-10	5289.9623	5289.9614	5289.9608	5289.9606		
0	5289.9640	5289.9631	5289.9626	5289.9622		
10	5289.9652	5289.9644	5289.9636	5289.9632		
20	5289.9655	5289.9650	5289.9643	5289.9633		
30	5289.9958	5289.9950	5289.9944	5289.9940		
40	5289.9975	5289.9969	5289.9968	5289.9960		
50	5289.9657	5289.9655	5289.9653	5289.9648		
Max. Deviation (MHz)	0.0396	0.0404	0.0408	0.0416		
Max. Deviation (ppm)	7.49	7.64	7.71	7.86		
Result	Pass					

 SPORTON INTERNATIONAL INC.
 Page No.
 : 253 of 256

 TEL: 886-3-3273456
 Report Version
 : Rev. 03

 FAX: 886-3-3270973
 Issued Date
 : Jan. 12, 2018

FCC ID: UDX-60067010



Voltage vs. Frequency Stability

Voltage	Measurement Frequency (MHz)				
(V)		5530 MHz			
	0 Minute	2 Minute	5 Minute	10 Minute	
126.50	5529.9659	5529.9650	5529.9640	5529.9634	
110.00	5529.9655	5529.9649	5529.9643	5529.9637	
93.50	5529.9651	5529.9650	5529.9640	5529.9633	
Max. Deviation (MHz)	0.0349	0.0351	0.0360	0.0367	
Max. Deviation (ppm)	6.31	6.35	6.51	6.64	
Result	Pass				

Temperature vs. Frequency Stability

Temperature vs. Frequency Stability									
Temperature	Measurement Frequency (MHz)								
(°C \	5530 MHz								
(°C)	0 Minute	2 Minute	5 Minute	10 Minute					
-20	5529.9623	5529.9619	5529.9617	5529.9611					
-10	5529.9640	5529.9637	5529.9633	5529.9631					
0	5529.9641	5529.9640	5529.9634	5529.9626					
10	5529.9651	5529.9641	5529.9637	5529.9633					
20	5529.9655	5529.9649	5529.9647	5529.9644					
30	5529.9958	5529.9955	5529.9947	5529.9941					
40	5529.9961	5529.9960	5529.9951	5529.9941					
50	5529.9663	5529.9656	5529.9646	5529.9639					
Max. Deviation (MHz)	0.0377	0.0381	0.0383	0.0389					
Max. Deviation (ppm)	6.82	6.89	6.93	7.03					
Result	Pass								

SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 254 of 256 Report Version : Rev. 03

Issued Date : Rev. 03 : Jan. 12, 2018



4 Test Equipment and Calibration Data

Instrument	Manufacturer	Model No.	Serial No.	Characteristics	Calibration Calibration Date Due Date		Remark
EMI Receiver	Agilent	N9038A	My52260123	9kHz ~ 8.45GHz	Jan. 23, 2017	Jan. 22, 2018	Conduction (CO01-CB)
LISN	F.C.C.	FCC-LISN-50-1 6-2	04083	150kHz~100MHz Dec. 14, 2016 Dec. 13, 2017		Conduction (CO01-CB)	
LISN	Schwarzbeck	NSLK 8127	8127647	9kHz ~ 30MHz	Dec. 21, 2016	Dec. 20, 2017	Conduction (CO01-CB)
COND Cable	Woken	Cable	01	150kHz ~ 30MHz	May 23, 2017	May 22, 2018	Conduction (CO01-CB)
Software	Audix	E3	6.120210n	-	N.C.R.	N.C.R.	Conduction (CO01-CB)
BILOG ANTENNA with 6dB Attenuator	TESEQ & EMCI	CBL6112D & N-6-06	37880 & AT-N0609	20MHz ~ 2GHz	Aug. 30, 2017	Aug. 29, 2018	Radiation (03CH01-CB)
Loop Antenna	Teseq	HLA 6120	24155	9kHz - 30 MHz	Mar. 16, 2016*	Mar. 15, 2018*	Radiation (03CH01-CB)
Horn Antenna	EMCO	3115	00075790	750MHz~18GHz	Nov. 10, 2016	Nov. 09, 2017	Radiation (03CH01-CB)
Horn Antenna	Schwarzbeck	BBHA 9170	BBHA9170252	15GHz ~ 40GHz	Jul. 05, 2017	Jul. 04, 2018	Radiation (03CH01-CB)
Pre-Amplifier	EMCI	EMC330N	980332	20MHz ~ 3GHz	May 02, 2017	May 01, 2018	Radiation (03CH01-CB)
Pre-Amplifier	Agilent	8449B	3008A02310	1GHz ~ 26.5GHz	Jan. 16, 2017	Jan. 15, 2018	Radiation (03CH01-CB)
Pre-Amplifier	MITEQ	TTA1840-35-HG	1864479	18GHz ~ 40GHz	Jul. 10, 2017	Jul. 09, 2018	Radiation (03CH01-CB)
Spectrum Analyzer	R&S	FSP40	100056	9kHz ~ 40GHz	Nov. 22, 2016	Nov. 21, 2017	Radiation (03CH01-CB)
EMI Test	R&S	ESCS	100355	9kHz ~ 2.75GHz	May 06, 2017	May 05, 2018	Radiation (03CH01-CB)
RF Cable-low	Woken	Low Cable-16+17	N/A	30 MHz ~ 1 GHz	Oct. 24, 2016	Oct. 23, 2017	Radiation (03CH01-CB)
RF Cable-high	Woken	High Cable-16	N/A	1 GHz ~ 18 GHz	Oct. 24, 2016	Oct. 23, 2017	Radiation (03CH01-CB)
RF Cable-high	Woken	High Cable-16+17	N/A	1 GHz ~ 18 GHz	Oct. 24, 2016	Oct. 23, 2017	Radiation (03CH01-CB)
RF Cable-high	Woken	High Cable-40G#1	N/A	18GHz ~ 40 GHz	Oct. 24, 2016	Oct. 23, 2017	Radiation (03CH01-CB)
RF Cable-high	Woken	High Cable-40G#2	N/A	18GHz ~ 40 GHz	Oct. 24, 2016	Oct. 23, 2017	Radiation (03CH01-CB)

SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 255 of 256
Report Version : Rev. 03
Issued Date : Jan. 12, 2018



Instrument	Manufacturer	Model No.	Serial No.	Characteristics	Calibration Date	Calibration Due Date	Remark
Test Software	Audix	E3	6.2009-10-7	N/A	N/A	N/A	Radiation (03CH01-CB)
Spectrum analyzer	R&S	FSV40	100979	9kHz~40GHz	Dec. 26, 2016	Dec. 25, 2017	Conducted (TH01-CB)
Temp. and Humidity Chamber	Ten Billion	TTH-D3SP	TBN-931011	-30~100 degree	Jun. 02, 2017	Jun. 01, 2018	Conducted (TH01-CB)
RF Cable-high	Woken	RG402	High Cable-6	1 GHz –26.5 GHz	Oct. 24, 2016	Oct. 23, 2017	Conducted (TH01-CB)
RF Cable-high	Woken	RG402	High Cable-7	1 GHz –26.5 GHz	Oct. 24, 2016	Oct. 23, 2017	Conducted (TH01-CB)
RF Cable-high	Woken	RG402	High Cable-8	1 GHz –26.5 GHz	Oct. 24, 2016	Oct. 23, 2017	Conducted (TH01-CB)
RF Cable-high	Woken	RG402	High Cable-9	1 GHz –26.5 GHz	Oct. 24, 2016	Oct. 23, 2017	Conducted (TH01-CB)
RF Cable-high	Woken	RG402	High Cable-10	1 GHz –26.5 GHz	Oct. 24, 2016	Oct. 23, 2017	Conducted (TH01-CB)
Power Sensor	Agilent	U2021XA	MY53410001	50MHz~18GHz	Nov. 22, 2016	Nov. 21, 2017	Conducted (TH01-CB)
Power Sensor	Agilent	U2021XA	MY53410002	50MHz~18GHz	Nov. 22, 2016	Nov. 21, 2017	Conducted (TH01-CB)

Note: Calibration Interval of instruments listed above is one year.

SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 FCC ID: UDX-60067010 Page No. : 256 of 256
Report Version : Rev. 03

Issued Date : Jan. 12, 2018

<sup>\*</sup>Calibration Interval of instruments listed above is two year.


N.C.R. means Non-Calibration required.

RSE Co-location Result								
Operating Mode	1	Polarization	Horizontal					
Operating Function	Normal Link							




	Freq	Level						Preamp Factor		T/Pos	Remark	Pol/Phase
	MHz	dBuV/m	dBuV/m	dB	dBuV	dB	dB/m	dB	cm	deg		
1	1910.48	37.11	54.00	-16.89	40.86	3.71	27.13	34.59	179	248	Average	HORIZONTAL
2	1917.58	46.58	74.00	-27.42	50.29	3.72	27.16	34.59	179	248	Peak	HORIZONTAL

**Operating Function** 



Normal Link



	Freq	Level						Preamp Factor		T/Pos	Remark	Pol/Phase
	MHz	dBuV/m	dBuV/m	dB	dBuV	dB	dB/m	dB	cm	deg		
1	1904.48	49.18	74.00	-24.82	52.95	3.71	27.11	34.59	100	287	Peak	VERTICAL
2	1918.18	36.70	54.00	-17.30	40.41	3.72	27.16	34.59	100	287	Average	VERTICAL