


1. Photographs of Conducted Emissions Test Configuration



Front view




Side view

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 1 of 4
EP Report Version : Rev. 01
Issued Date : Jul. 19, 2018





**Under Table View** 

SPORTON International Inc.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 2 of 4

EP Report Version : Rev. 01

Issued Date : Jul. 19, 2018



# 2. Photographs of Radiated Emissions Test Configuration For radiated emissions below 1G



Front view




Rear view

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 3 of 4 EP Report Version : Rev. 01 Issued Date : Jul. 19, 2018



### For radiated emissions above 1GHz



### Front view



#### Rear view

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 4 of 4
EP Report Version : Rev. 01
Issued Date : Jul. 19, 2018