Mr. Fujimoto:

In order for processing of this application (FCC ID: T64282000902) to continue, the following issue(s) will have to be addressed:

- 1) The grantee code used on the application is invalid for the applicant.
- 2) An invalid grantee code is used on the FCC ID.
- 3) The phrase "FCC ID:" and the FCC ID itself must be on the same line.
- 4) The signed copy of the test report needs to be submitted.
- 5) The modification mentioned in the report does not appear to be complete. Please list the entire modification that was performed.
- The spurious emissions data from 6.3 GHz to 9.3 GHz was not submitted. Please submit.
- 7) A modification letter was not submitted.
- 8) FYI It should be noted that the FCC ID is permitted to be located in the battery compartment only if the it is visible when it is initially removed from its packaging, for instance if the device is sold with the batteries and battery cover removed.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Please upload responses and/or exhibits to the electronic filing website.

Your correspondence number is T64282000902-1.