## Correspondence by Project

## Project Number:

-1998891581

Correspondence Number	Memo
T64282400902-1	1) The grantee code used on the application is invalid for the applicant. Response: The grantee code has been updated. 2) An invalid grantee code is used on the FCC ID. Response: The FCC-ID Label has been revised to show the correct FCC ID. 3) The phrase "FCC ID:" and the FCC ID itself must be on the same line. Response: The FCC-ID Label has been revised to show the FCC ID itself on the same line. 4) The frequency of operation on the 731 form and the frequency of operation on the test report do not match. Please clarify. Response: Response: The grantee code has been updated. 5) A letter stating Response: This statement is incomplete and thus no action taken. 6) A Letter of Authority must be submitted. Response: The letter of authority has been uploaded. 7) FYI – It should be noted that the FCC ID is permitted to be located in the battery compartment only if the it is visible when it is initially removed from its packaging, for instance if the device is sold with the batteries and battery cover removed. Response: Noted.