

Gajah International (HK) Co.,Ltd

18/F Bel Trade Commercial Building, 1-3, Burrows Street, Wan Chai, Hong Kong. **Tel:** +852-6326 5997

Attestation Letter

July 11, 2013

To:
Bay Area Compliance Laboratories Corp.
1274 Anvilwood Avenue
Sunnyvale, CA 94089

Dear Sir or Madam:

The chipset, model MT6162, installed in our product 7"MID, model: MD7011, FCC ID:UFKMD701100; our product 8"MID, model: MD8005, FCC ID: UFKMD800500 which support GSM/GPRS/WCDMA functions. For using in the EU and US this chip will not support/enable the GSM/GPRS/WCDMA function. The GSM/GPRS/WCDMA function has been shielded by the manufacturer using the software.

The chipset, model MT6620, installed in our product 7"MID, model: MD7011, FCC ID:UFKMD701100; our product 8"MID, model: MD8005, FCC ID: UFKMD800500 which support support BT 3.0/BT4.0 functions. For using in the EU and US this chip will not support/enable the BT 4.0 function. The BT 4.0 function has been shielded by the manufacturer using the software.

Best Regards,

Signature:

Ying Keong Chaw Vice President