

Report reference No: KST-FCC0622

Inside



Port



KOSTEC Co.,Ltd.
180-254,Annyung-Ri, Taean-Yup, Hwasung-shi, Kyunggi-do, Korea Tel: +82-31-222-4251 Fax: +82-31-222-4252 http://www.kosteclab.com



Page : 15of 22 July 20, 2006


Report reference No: KST-FCC0622



A/D Board (Front)



A/D Board (Rear)










Report reference No: KST-FCC0622

OSD Board (Front)











Report reference No: KST-FCC0622

LCD Panel (Front)



LCD Panel (Rear)



KOSTEC Co.,Ltd.
180-254,Annyung-Ri, Taean-Yup, Hwasung-shi, Kyunggi-do, Korea Tel: +82-31-222-4251 Fax: +82-31-222-4252 http://www.kosteclab.com




Page : 18of 22 July 20, 2006


Report reference No: KST-FCC0622



SMPS (Front)







KOSTEC Co.,Ltd.
180-254,Annyung-Ri, Taean-Yup, Hwasung-shi, Kyunggi-do, Korea Tel: +82-31-222-4251 Fax: +82-31-222-4252 http://www.kosteclab.com



Page : 19of 22 July 20, 2006


Report reference No: KST-FCC0622



I/O Board (Front)



I/O Board (Rear)





Report reference No: KST-FCC0622



TV TUNER Board (Front)



TV TUNER Board (Rear)

