



Appendix B. Setup Photographs

Conducted Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-328-4978

FCC ID: UFOBC0164AAA390

Page Number : B2 of B4
Report Issued Date : Aug. 12, 2008
Report Version : Rev. 02





SIDE VIEW


SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UFOBC0164AAA390 Page Number : B3 of B4
Report Issued Date : Aug. 12, 2008
Report Version : Rev. 02






Radiation Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UFOBC0164AAA390 Page Number : B4 of B4
Report Issued Date : Aug. 12, 2008
Report Version : Rev. 02