
# Appendix C. Set up Photograph

## **Conducted Emission**

Mode 1~2



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390 Page Number : C1 of C6
Report Issued Date : Jul, 17, 2007
Report Version : Rev. 01

Report No. : FR762206-A



SIDE VIEW

Mode 3~5




FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390 Page Number : C2 of C6
Report Issued Date : Jul, 17, 2007
Report Version : Rev. 01





**REAR VIEW** 



SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390 Page Number : C3 of C6
Report Issued Date : Jul, 17, 2007
Report Version : Rev. 01



Mode 4




FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390 Page Number : C4 of C6
Report Issued Date : Jul, 17, 2007
Report Version : Rev. 01




SIDE VIEW

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390 Page Number : C5 of C6
Report Issued Date : Jul, 17, 2007
Report Version : Rev. 01



### **Radiation Emission**



### **FRONT VIEW**



### **REAR VIEW**

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UFOBC0164AAA390 Page Number : C6 of C6 Report Issued Date : Jul, 17, 2007

Report Version : Rev. 01