## Appendix C. Set up Photograph Spurious Radiation



FRONT VIEW

**REAR VIEW** 



SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C1
Report Issued Date : Mar. 20, 2007
Report Version : Rev. 01

**Report No. : FG721401**