


## Appendix C. Set up Photograph

## Spurious Radiation

Mode 1-3



**Report No.: FG690517** 

FRONT VIEW

REAR VIEW



SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C2

Report Issued Date : Sep. 28, 2006

Report Version : Rev. 01

C TEST REPORT Report No. : FG690517

## Mode 4-6

**FRONT VIEW** 

## 690517

**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C2
Report Issued Date : Sep. 28, 2006
Report Version : Rev. 01

690517