

Report No.: 06147071

Talk Mode


Tested By:Hong, Report No.:06147071

Scan Settings (1 Range)

|------ Frequencies -------| Receiver Settings -------|
Start Stop Step IF BW Detector M-Time Atten Preamp OpRge
150k 30M 5k 10k PK+AV 10ms AUTO LN OFF 60dB

Final Measurement: x QP / + AV

Meas Time: 1 s Subranges: 16 Acc Margin: 20dB Transducer No. Start Stop Name 2 1 9k 30M EW0699 12 9k 30M EW0192



Ctrl No.: N/A



Report No.: 06147071

Talk Mode

Tested By:Hong, Report No.:06147071

Scan Settings (1 Range)

|------ Frequencies -----||----- Receiver Settings -----|

Start Stop Step IF BW Detector M-Time Atten Preamp OpRge 150k 30M 5k 10k PK+AV 10ms AUTO LN OFF 60dB

Final Measurement Results:

no Results

Ctrl No.: N/A