

Report No.: 06176311

Talk Mode


Tested By:Hong, Report No.:06176311

Scan Settings (1 Range)

|------ Frequencies ------||----- Receiver Settings -----| Step IF BW Detector M-Time Atten Preamp OpRge
5k 10k PK+AV 10ms AUTO LN OFF 60dB Start Stop 150k 30M

Transducer No. Start Stop Name 2 1 9k 30M EW0699 12 9k 30M EW0192 Final Measurement: x QP / + AV

Meas Time: 1 s Subranges: 16 Acc Margin: 20dB



Ctrl No.: N/A



Report No.: 06176311

Talk Mode

Tested By:Hong, Report No.:06176311

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start Stop Step IF BW Detector M-Time Atten Preamp OpRge
150k 30M 5k 10k PK+AV 10ms AUTO LN OFF 60dB

Final Measurement Results:

Frequency QP Level QP Limit

MHz dBuV dBuV

no Results

Frequency AV Level AV Limit
MHz dBuV dBuV

25.05500 34.2 50.0

* limit exceeded

Ctrl No.: N/A