
TEST SETUP PHOTOGRAPHS


1. AC input power measurement



2. Conducted Emission Test



3. Operation frequency measurement



4. Radiated emission measurement



5. Radiation hazard test



6. RF output power measurement

