



To whom it may concern,

There is no tune-up procedure for the Autocite X3.

The Autocite X3 module is fully aligned in the factory and needs no further adjustment

Dated this 16 day of August 2006.

Title: Chief Technology Officer

Gavin Jones

Telephone: +61.2.9432.0500