



Report No.: FR5D2512AC

## **Appendix A. Test Photos**

1. Photographs of Conducted Emissions Test Configuration



**FRONT VIEW** 




**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A1 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01





Report No. : FR5D2512AC



**SIDE VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01






## 1 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A3 of A5

Report Version

: Rev. 01


Report No.: FR5D2512AC





Report No. : FR5D2512AC

For radiated emissions 30MHz~1GHz



**FRONT VIEW** 



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A4 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report

Report No. : FR5D2512AC

## For radiated emissions above 1GHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A5 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01