

8-22-2006

Federal Communications Commission 445 12th Street, SW Washington, DC 20554

RE: Change in Identification for Cisco Systems Inc FCCID: LDK102056

To Whom It May Concern:

Tessco Technologies (FRN – 0015379811, Grantee Code – UII) is requesting a change in Identification for Cisco Systems Inc. 802.11a/b/g Access Point (FCCID: LDK102056), original granted on 31 August 2005.

Tessco Technologies is not modifying the 802.11a/b/g Access Point in any way. The original test results continue to be representative of and applicable to the equipment bearing the changed identification. The only change will be in the FCCID to reflect the Tessco Technologies Grantee Code of UII. Therefore, we are requesting that the new identification be FCCID: UII102056.

Enclosed are the label exhibit and the external photograph exhibit required as per the FCC's requirement for a change in identification request. Please feel free to contact me directly if there are any questions or concerns.

Best Regards,

Chris Marco

WLAN PBU Leader

Tessco Technologies, Inc.