
Rhein Tech Laboratories, Inc. 360 Herndon Parkway Suite 1400 Herndon, VA 20170 http://www.rheintech.com

Client: Itowa
Model: ICFM
Standard: FCC 15.247
FCC ID: UIWICFM01ITW
Report #: 2006097


Appendix L: Internal Photographs



Photograph 12: Top with Shield Removed


Rhein Tech Laboratories, Inc. 360 Herndon Parkway Suite 1400 Herndon, VA 20170 http://www.rheintech.com

Client: Itowa
Model: ICFM
Standard: FCC 15.247
FCC ID: UIWICFM01ITW
Report #: 2006097




Photograph 13: Top with RF PCB and Shield Removed

Client: Itowa
Model: ICFM
Standard: FCC 15.247
FCC ID: UIWICFM01ITW
Report #: 2006097



Photograph 14: Top of RF PCB

Client: Itowa
Model: ICFM
Standard: FCC 15.247
FCC ID: UIWICFM01ITW
Report #: 2006097



Photograph 15: Bottom of RF PCB